



North Bank Playground

Completed By: Patrick McCord

Date of Report: April 15, 2020

Time of Observation: 1:00 PM

1. WEATHER							
	Clear	PM	Calm		<10 deg		61-70 deg
PM	P/Cloudy		Slight Breeze		11-20 deg		70-80 deg
	Overcast		Moderate Winds		21-32 deg		80-90 deg
	Rain		Windy		33-45 deg		91-99 deg
	Smokey		Very Windy +35mph	PM	45-60 deg		100+
	Snow						
2. CONSTRUCTION ACTIVITY							
Area	Observation						
Site	Storm water structure, pipe bedding and piping has been installed at east parking lot area. West retaining wall being formed at skate park. West side site retaining wall has been formed. East side drywell has been installed in the swale.						
Building	Test pile has been installed.						
3. LABOR (REPORTED FROM GENERAL CONTRACTOR)							
Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers	Contractor	# Of Workers
T LaRiviere	11		0				0
Budinger	03						
4. EQUIPMENT ON SITE							
Type of Equipment	#	Type of Equipment	#	Type of Equipment	#	Type of Equipment	#
Compaction roller	1	Dozer	1	Track hoe			3
Terex dumptruck	1	Front loader	1	Water truck			1
Bobcat	1	Extended forklift	1	Track hoe with hammer			0
Man lift	0	Mini track hoe	1	Extended manlift			1
5. TPZ							
•							
6. DELIVERIES & CONDITIONS Note time and type of delivery							
•							
7. FIELD DISCUSSIONS OR NOTES (provide bulleted list of discussions, directions or decisions)							
•							
8. SCHEDULE REVIEW							
•							
9. PROJECT PHOTOGRAPHS							
• See pictures below:							



North Bank Playground

Completed By: Patrick McCord

Date of Report: April 15, 2020

Time of Observation: 1:00 PM



#1 View from cliff east side of the cliff (facing south).



#2 View from east side of the cliff (facing west).



#3 View from west ramp (facing east).



#4 West retaining wall at skate park



#5 East side stock piles.



#6 West side site retaining wall.



7 East side drywell.



#8 Test pile.



#9 Stormwater inlet.